Scope of	Work for Property Lo	cate	d at	:		3072	-74 North	34th Stre	<u>eet</u>	
	Property is: Single Far	nily		Dup	olex	V	Other□			
Date:	6/9/2015									
take no respo	minimum requirement to meet he onsibility for problems discovered a by private lenders, insurance cor	after th	e insp	ection	date	e, or for c	missions throu	gh error or o	versight. The	
Exterior	Condition Report									
Location Site	Required Work Landscaping	n/a	<u> </u>	Yes		Note/ Self He	Comments elp			\$ Cost
	Steps/Handrails	n/a		Yes	V	handra	nil			\$ 125.00
	Service walks	n/a		Yes	V					\$ 650.00
	Fencing	n/a	V	Yes						\$
	Parking	n/a	V	Yes						\$
	Retaining walls	n/a	V	Yes						\$
	Other	n/a		Yes						\$
	Other	n/a		Yes						\$
Garage	Singles: repair	n/a	V	Yes						\$
	Shingles: Roof over existing	n/a	V	Yes		_				\$
	Shingles:Tear off & re-roof	n/a		Yes	V	includi	ng structural			\$ 7,200.00
	Gutters/downspouts	n/a	V	Yes						\$
	Flashing	n/a	V	Yes						\$
	Eaves	n/a	V	Yes						\$
	Siding	n/a		Yes	V					\$ 150.00
	Doors	n/a		Yes	V	service	•			\$ 375.00
	Windows	n/a	V	Yes						\$
	Slab	n/a	V	Yes						\$
	Paint	n/a		Yes	V	wood	surfaces			\$ 750.00
	Electrical	n/a	V	Yes		_				\$
_	Other	n/a		Yes	V	raze sh	ned behind gar	rage		\$ 2,000.00
Porches	Roof	n/a	V	Yes						\$
	Deck-upper	n/a		Yes	V	include	es removing ex	xterior stairs	s to attic	\$ 4,600.00
	Decklower	n/a		Yes	V	repair				\$ 1,400.00
	Steps/handrails	n/a		Yes	V	hand/g	uardrail @ ste	ps		\$ 375.00
	Ceiling	n/a	7	Yes						\$
	Guardrails	n/a	V	Yes						\$
	Structural	n/a	V	Yes						\$
	Paint	n/a		Yes	V					\$ 600.00

n/a ☐ Yes ☑ permit

Other

85.00

\$

House

Chimney	n/a ☑	Yes □		\$
Shingles: repair	n/a ☑	Yes 🗆		\$
Shingles: Roof over existing	n/a ☑	Yes 🗆		\$
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 10,200.00
Gutters/downspouts	n/a □	Yes ✓	_	\$ 1,008.00
Flashing	n/a ☑	Yes 🗆		\$
Eaves	n/a □	Yes ☑		\$ 350.00
Siding	n/a ☑	Yes 🗆		\$
Storm Doors	n/a ☑	Yes □		\$
Prime ("main") Doors	n/a □	Yes ☑		\$ 700.00
Storm Windows	n/a ☑	Yes □		\$
Prime ("main") Windows	n/a □	Yes ☑		\$ 930.00
Paint	n/a 🔲	Yes ☑	previously painted surfaces	\$ 3,200.00
Foundation	n/a ☑	Yes 🗆		\$
Electrical	n/a □	Yes ☑	disconnect 2 services	\$ 1,000.00
Other	n/a 🗆	Yes ☑	window screens	\$ 400.00
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$

Exterior: Estimated Cost:* \$ 36,098.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

interior Co	onaition Report					
Maahaniaal	Unit: Entire unit (single family) Upper unit of duplex				Lower unit of duplex ○ Other □	
Mechanical Heating	Required Work					
	Repair/replace boiler	n/a ☑	Yes		==	\$
	Repair radiation	n/a ☑	Yes			\$
	Repair/replace furnace	n/a ☑	Yes			\$
	Repair ductwork	n/a ☑	Yes			\$
	Replace thermostat	n/a ☑	Yes			\$
	Repair/replace grilles	n/a ☑	Yes			\$
Flootvicel	Tune boiler/furn. insp ht exchang	j∈n/a □	Yes	V		\$ 350.00
Electrical	Repair/replace receptacles	n/a □	Yes	V		\$ 800.00
	Repair/replace switches	n/a □	Yes	V		\$ 800.00
	Repair/replace fixtures	n/a □	Yes	V		\$ 800.00
	Install outlets and circuits	n/a ☑	Yes			\$
	Install outlets and circuits	n/a ☑	Yes			\$
	Install outlets and circuits	n/a ☑	Yes			\$
	Install outlets and circuits	n/a ☑	Yes			\$
	Upgrade service	n/a ☑	Yes			\$
	Other	n/a □	Yes	V	permit	\$ 85.00
	Other	n/a □	Yes	V	basement wiring to appliances, etc	\$ 600.00
Plumbing	Repair/replace kitchen sink	n/a □	Yes			\$
	Repair/replace kitchen sink fauce	ein/a □	Yes			\$
	Repair/replace tub	n/a □	Yes			\$
	Repair/replace tub faucet	n/a □	Yes			\$
	Repair/replace toilet	n/a □	Yes			\$
	Repair/replace lavatory	n/a □	Yes			\$
	Repair/replace lavatory faucet	n/a □	Yes			\$
	Repair/replace wash tub	n/a □	Yes			\$
	Repair/replace wash tub faucet	n/a □	Yes			\$
	Other	n/a □	Yes	V	permit	\$ 85.00
	Repair drain/waste/vent piping	n/a □	Yes	V	includes in basement	\$ 600.00
	Repair water piping	n/a □	Yes	V	includes in basement	\$ 600.00
	Repair/replace water heater	n/a □	Yes	V	service	\$ 350.00
	Other	n/a □	Yes	V	complete kitchen	\$ 1,455.00
	Other	n/a □	Yes	V	complete bathroom	\$ 2,170.00

760.00
220.00
1,200.00
800.00
55.00
110.00
248.00
900.00
3,600.00
3,000.00

Interior Co	ondition Report								
Mochanical	Unit: Entire unit (single family) Upper unit of duplex Required Work	□				Lower unit of duplex Other			
Heating	riequired Work								
	Repair/replace boiler	n/a	✓	Yes				\$ <u> </u>	
	Repair radiation	n/a	V	Yes				\$ i	
	Repair/replace furnace	n/a	V	Yes				\$ 1	
	Repair ductwork	n/a	V	Yes				\$ l	
	Replace thermostat	n/a	V	Yes				\$ i	
	Repair/replace grilles	n/a	V	Yes				\$ i	
Electrical	Tune boiler/furn. insp ht exchang	€n/a		Yes	V			\$ i	350.00
Liectifical	Repair/replace receptacles	n/a		Yes	V			\$ 1	800.00
	Repair/replace switches	n/a		Yes	V			\$ 1	800.00
	Repair/replace fixtures	n/a		Yes	V			\$ l	800.00
	Install outlets and circuits	n/a	V	Yes				\$ i	
	Install outlets and circuits	n/a	V	Yes				\$ i	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$ 1	
	Upgrade service	n/a	V	Yes				\$ 1	
	Other	n/a		Yes	V	permit		\$ i .	85.00
	Other	n/a		Yes				\$ 1	
Plumbing	Repair/replace kitchen sink	n/a		Yes				\$ 1	
	Repair/replace kitchen sink fauce	ein/a		Yes				\$ <u> </u>	
	Repair/replace tub	n/a		Yes				\$	
	Repair/replace tub faucet	n/a		Yes		_		\$ i	
	Repair/replace toilet	n/a		Yes				\$	
	Repair/replace lavatory	n/a		Yes				\$ 1	
	Repair/replace lavatory faucet	n/a		Yes				\$	
	Repair/replace wash tub	n/a		Yes				\$ 1	
	Repair/replace wash tub faucet	n/a		Yes				\$ i	
	Unclog piping:	n/a		Yes				\$ i	
	Repair drain/waste/vent piping	n/a		Yes	V	_		\$ i	700.00
	Repair water piping	n/a		Yes	V			\$ 	700.00
	Repair/replace water heater	n/a		Yes	V	service		\$ 	350.00
	Other	n/a		Yes	V	complete kitchen		\$ 1	1,455.00

n/a ☐ Yes ☑ complete bathroom

2,170.00

Other

Windows					
	Replace broken glass	n/a ☑	Yes		\$
	Repair or replace sash	n/a ☑	Yes 🗆		\$
Doors	Repair or replace doors	n/a <u></u>	Yes ☑		\$ 950.00
	Repair or repl. locks/latches	n/a □	Yes ☑	Self Help	\$ 275.00
Walls/Ceiling	9				
	Repair or repl. @ defective	n/a □	Yes ☑		\$ 1,200.00
Paint	Repair or repl. @ defective	n/a □	Yes ✓		\$ 700.00
Fire Safety					
	Install smoke/CO alarm:bsmt.	n/a ☑	Yes □	Self Help	\$
	Install smoke/CO alarm: 1st flr.	n/a ☑	Yes 🗆	Self Help	\$
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes ☑	Self Help	\$ 165.00
Handrails	Repair/replace defective	n/a □	Yes ☑	Self Help	\$ 248.00
Stairs	Repair defective	n/a ☑	Yes 🗆		\$
Floors	Repair defective	n/a □	Yes ☑		\$ 1,400.00
Other		n/a □	Yes ☑	Note: Attic Cannot Be Used As Habitable Unit	\$ 5,000.00
		n/a 🔲	Yes 🗆	Without 2nd Legal Means Of Egress - Return	\$
		n/a □	Yes □	Area To Storage Space	\$
		n/a □	Yes 🗆		\$
				Interior: Estimated Cost:	\$ 34,736.00
				Total Exterior and Interior Cost:*	\$ 70,834.00

Inspected by: Tom Frank Date: 6/9/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $[\]ensuremath{^*}\text{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.